




SRD 5MHz_Ant5_5732.5




SRD 5MHz_Ant4_5787.5




SRD 5MHz_Ant5_5787.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant4_5842.5




SRD 5MHz_Ant5_5842.5




SRD 10MHz_Ant4_5157


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant5_5157




SRD 10MHz_Ant4_5162




SRD 10MHz_Ant5_5162


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant4_5163




SRD 10MHz_Ant5_5163




SRD 10MHz_Ant4_5164


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant5_5164




SRD 10MHz_Ant4_5165




SRD 10MHz_Ant5_5165


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant4_5166




SRD 10MHz_Ant5_5166




SRD 10MHz_Ant4_5167


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant5_5167




SRD 10MHz_Ant4_5168




SRD 10MHz_Ant5_5168


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant4_5169




SRD 10MHz_Ant5_5169




SRD 10MHz_Ant4_5170


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant5_5170




SRD 10MHz_Ant4_5201




SRD 10MHz_Ant5_5201


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant4_5245




SRD 10MHz_Ant5_5245




SRD 10MHz_Ant4_5730.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant5_5730.5




SRD 10MHz_Ant4_5787.5




SRD 10MHz_Ant5_5787.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant4_5844.5




SRD 10MHz_Ant5_5844.5




SRD 20MHz_Ant4_5161


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant5_5161




SRD 20MHz_Ant4_5162




SRD 20MHz_Ant5_5162


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant4_5163




SRD 20MHz_Ant5_5163




SRD 20MHz_Ant4_5164


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant5_5164




SRD 20MHz_Ant4_5165




SRD 20MHz_Ant5_5165


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant4_5166




SRD 20MHz_Ant5_5166




SRD 20MHz_Ant4_5167


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant5_5167




SRD 20MHz_Ant4_5168




SRD 20MHz_Ant5_5168


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant4_5169




SRD 20MHz_Ant5_5169




SRD 20MHz_Ant4_5170


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant5_5170




SRD 20MHz_Ant4_5171




SRD 20MHz_Ant5_5171


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant4_5200




SRD 20MHz_Ant5_5200




SRD 20MHz_Ant4_5240


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant5_5240




SRD 20MHz_Ant4_5735.5




SRD 20MHz_Ant5_5735.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant4_5787.5




SRD 20MHz_Ant5_5787.5




SRD 20MHz_Ant4_5839.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 20MHz_Ant5_5839.5



SRD 40MHz_Ant4_5170



SRD 40MHz_Ant5_5170

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.