




SRD 1.4MHz_Ant4_5166




SRD 1.4MHz_Ant5_5166




SRD 1.4MHz_Ant4_5168


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 1.4MHz_Ant5_5168




SRD 1.4MHz_Ant4_5202




SRD 1.4MHz_Ant5_5202


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 1.4MHz_Ant4_5248




SRD 1.4MHz_Ant5_5248




SRD 1.4MHz_Ant4_5728.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 1.4MHz_Ant5_5728.5




SRD 1.4MHz_Ant4_5786.5




SRD 1.4MHz_Ant5_5786.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 1.4MHz_Ant4_5846.12




SRD 1.4MHz_Ant5_5846.12




SRD 3MHz_Ant4_5154


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant5_5154




SRD 3MHz_Ant4_5157




SRD 3MHz_Ant5_5157


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant4_5160




SRD 3MHz_Ant5_5160




SRD 3MHz_Ant4_5163


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant5_5163




SRD 3MHz_Ant4_5166




SRD 3MHz_Ant5_5166


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant4_5202




SRD 3MHz_Ant5_5202




SRD 3MHz_Ant4_5247


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant5_5247




SRD 3MHz_Ant4_5727.5




SRD 3MHz_Ant5_5727.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant4_5787.2




SRD 3MHz_Ant5_5787.2




SRD 3MHz_Ant4_5847.2


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 3MHz_Ant5_5847.2




SRD 5MHz_Ant4_5155




SRD 5MHz_Ant5_5155


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant4_5157




SRD 5MHz_Ant5_5157




SRD 5MHz_Ant4_5162


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant5_5162




SRD 5MHz_Ant4_5167




SRD 5MHz_Ant5_5167


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant4_5202




SRD 5MHz_Ant5_5202




SRD 5MHz_Ant4_5247


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant5_5247




SRD 5MHz_Ant4_5732.5




SRD 5MHz_Ant5_5732.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant4_5787.5




SRD 5MHz_Ant5_5787.5




SRD 5MHz_Ant4_5842.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 5MHz_Ant5_5842.5




SRD 10MHz_Ant4_5157




SRD 10MHz_Ant5_5157


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant4_5162




SRD 10MHz_Ant5_5162




SRD 10MHz_Ant4_5163


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 10MHz_Ant5_5163



SRD 10MHz_Ant4_5164



SRD 10MHz_Ant5_5164

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.