




SRD 40MHz_Ant4_5173




SRD 40MHz_Ant5_5173




SRD 40MHz_Ant4_5178


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant5_5178




SRD 40MHz_Ant4_5180




SRD 40MHz_Ant5_5180


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant4_5186




SRD 40MHz_Ant5_5186




SRD 40MHz_Ant4_5188


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant5_5188




SRD 40MHz_Ant4_5189




SRD 40MHz_Ant5_5189


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant4_5190




SRD 40MHz_Ant5_5190




SRD 40MHz_Ant4_5200


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant5_5200




SRD 40MHz_Ant4_5230




SRD 40MHz_Ant5_5230


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant4_5745.5




SRD 40MHz_Ant5_5745.5




SRD 40MHz_Ant4_5787.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 40MHz_Ant5_5787.5




SRD 40MHz_Ant4_5829.5




SRD 40MHz_Ant5_5829.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant4_5180




SRD 60MHz_Ant5_5180




SRD 60MHz_Ant4_5181


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant5_5181




SRD 60MHz_Ant4_5182




SRD 60MHz_Ant5_5182


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant4_5186




SRD 60MHz_Ant5_5186




SRD 60MHz_Ant4_5188


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant5_5188




SRD 60MHz_Ant4_5191




SRD 60MHz_Ant5_5191


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant4_5193




SRD 60MHz_Ant5_5193




SRD 60MHz_Ant4_5195


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant5_5195




SRD 60MHz_Ant4_5196




SRD 60MHz_Ant5_5196


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant4_5200




SRD 60MHz_Ant5_5200




SRD 60MHz_Ant4_5220


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant5_5220




SRD 60MHz_Ant4_5755.5




SRD 60MHz_Ant5_5755.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant4_5787.5




SRD 60MHz_Ant5_5787.5




SRD 60MHz_Ant4_5819.5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 60MHz_Ant5_5819.5




SRD 80MHz_Ant4_5190




SRD 80MHz_Ant5_5190


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 80MHz_Ant4_5191




SRD 80MHz_Ant5_5191




SRD 80MHz_Ant4_5195


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



SRD 80MHz_Ant5_5195



SRD 80MHz_Ant4_5198



SRD 80MHz_Ant5_5198

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.