



September 11, 2015

Compliance Testing LLC
1724 S. Nevada Way
Mesa, AZ 85204

ATTESTATION for RM5, FCC ID: SWX-R5M

To Whom It May Concern:

This letter serves as a description for "Bridge Mode" compliance in the DFS bands (UNII 2). "Bridge Mode" is normal operation for either a MASTER or CLIENT and has been tested under 15.407 DFS and is compliant.

Please contact me if there is any information you may need.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Michael Taylor', with a stylized flourish extending to the right.

Michael Taylor
Compliance Manager
2580 Orchard Parkway
San Jose, CA 95131, USA
408-942-3085
compliance@ubnt.com