





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos





Test Report Number: 17040084HKG-001, 17040084HKG-002
FCC ID: SXO-C001
IC: 10016A-C001

INTERTEK TESTING SERVICES

Internal photos



Internal photos



Test Report Number: 17040084HKG-001, 17040084HKG-002
FCC ID: SXO-C001
IC: 10016A-C001



INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17040084HKG-001, 17040084HKG-002
FCC ID: SXO-C001
IC: 10016A-C001



INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 17040084HKG-001, 17040084HKG-002
FCC ID: SXO-C001
IC: 10016A-C001



Internal photos



Test Report Number: 17040084HKG-001, 17040084HKG-002
FCC ID: SXO-C001
IC: 10016A-C001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17040084HKG-001, 17040084HKG-002
FCC ID: SXO-C001
IC: 10016A-C001


INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

