



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004
FCC ID: SXO-SP001
IC: 10016A-SP001