

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.
No.666 Hu'an Rd. Huli District Xiamen City, Fujian, P.R. China
Tel: 86-592-5702000
Fax: 86-592-5702455
Email: chenjl@yealink.com

FCC certification No. Cover Letter

Date: 2026-07-06

We, YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD., hereby submit justification for placing the FCC certification No. in the associated user's manual and packaging.

According to the FCC regulation, the FCC certification No. should be printed on the product, but as the product are too small to print the label (FCC ID: T2C-BHD862L) , it will be moved to the user manual and packaging. The details are as below:

- A. Side surface (A): The side surface does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.




- B. Top cover (B): The top cover does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the user's manual and packaging.

Label:



The label is in the user manual and packaging.

Sincerely Yours,

Signature:

Stone Lu

Stone Lu

Vice General Manager