

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.
No.666 Hu'an Rd. Huli District Xiamen City, Fujian, P.R. China
Tel: 86-592-5702000
Fax: 86-592-5702455
Email: chenjl@yealink.com

Date: 2025-03-28

Attestation Letter

FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046


Dear Sir/Madam,

The RF Module, model: YL43752, installed in our product Collaboration Board, Model: MeetingBoard 75 Pro; FCC ID: T2C-IWB75PRO, for marketing purpose, this module only supports BLE 1M; 2.4G Wi-Fi (2412-2462MHz; 802.11b/g/n20/ax20 mode); 5G Wi-Fi (5150-5250MHz, 5250-5350MHz, 5470-5725MHz, 5725-5850MHz; 802.11a/n20/n40/ac20/ac40/ac80/ax20/ax40/ax80 mode). The other functions, bands and modes were disabled to use by manufacture in the software, and for 802.11ax mode, it only supports full RU configuration not partial RU, the partial RU was also disabled by software, the end user has no capability to activate it.

The RF Module, model: YL7981, installed in our product Collaboration Board, Model: MeetingBoard 75 Pro; FCC ID: T2C-IWB75PRO, for marketing purpose, this module only supports 5G Wi-Fi (5150-5250MHz, 5725-5850MHz; 802.11a/n20/n40/ac20/ac40/ac80/ax20/ax40/ax80 mode). The other functions, bands and modes were disabled to use by manufacture in the software, and for 802.11ax mode, it only supports full RU configuration not partial RU, the partial RU was also disabled by software, the end user has no capability to activate it.

Sincerely Yours,

Signature:



Stone Lu
Vice General Manager