

# Yealink

# MCORE Max



# Quick Start Guide V1.0

# Package Contents



(1.8 m, 5.91 ft)

HDMI Cable



Power Adapter



We recommend that you use the accessories provided or approved by Yealink. The use of unapproved third-party accessories may result in poor performance.

# Hardware Interface


1. Internet Port: connect to the external.
2. USB Port: connect to USB devices.
3. HDMI Port: connect to displays.
4. HDMI in: auxiliary input.
5. VCH Port: connect to Touch Panel.
6. Dante(Audio) Port: connect to IP audio and video device.
7. AVoip Port: connect to central control device.
8. Reset Port: reset the device.
9. -100-240V: connect to the power adapter.



# MCore Max Installation

## • Mount in a Rack

Install the mounting ears to the sides of the MCore Max.



Push the MCore Max into the rack, and then fix it to the rack with screws.