


View of Inside

Component side view of Main board



Report no. ETLE060213.056, Page D2 of D9


Solder side view of Main board




Component side view of HDD



Solder side view of HDD



Component side view of LCD Panel



Solder side view of LCD Panel



Component side view of Adapter



Solder side view of Adapter



View of Adapter Label



Inside view of Adapter



View of Cable



View of Cradle

