


Scott Health & Safety Division of Scott Technologies, Inc.

Pak Tracker Locator System

FCC ID#: T5E-200396

Photo One – Internal Open for Inspection




**Scott Health & Safety Division of Scott
Technologies, Inc.**

Pak Tracker Locator System

FCC ID#: T5E-200396

**Photo Two – Internal
Radio/RF Section Shielded
PCB Antenna to the Right**




**Scott Health & Safety Division of Scott
Technologies, Inc.**

Pak Tracker Locator System

FCC ID#: T5E-200396

**Photo Three – Internal
Shield Removed. RF Section Close-Up**




**Scott Health & Safety Division of Scott
Technologies, Inc.**

Pak Tracker Locator System

FCC ID #: T5E-200396


**Photo Four – Internal
PCB Antenna**



**Scott Health & Safety Division of Scott
Technologies, Inc.**

**Pak Tracker Locator System
FCC ID#: T5E-200396**

**Photo Five – Internal
PCB Flip-Side of RF Section / PCB Antenna**



Scott Health & Safety Division of Scott Technologies, Inc.

**Pak Tracker Locator System
FCC ID #: T5E-200396**

**Photo Six – Internal
PCB Side**

