



Manufacturer
ZhuHai LongXin Technology Co.,Ltd,
No.6 Guangtian 1st Road, Pingsha Town, Jinwan District,Zhuhai, China


H200
TEST GUIDE AND
ANTENNA GAIN

GUIDE HOW TO BURST WITH RADIATED UNIT


Press Menu and type *987*




Press Tx Burs




Select Channel




Select Antenna



ANTENNA 1 LOCATION




ANT1 GAIN $\Phi=90^\circ$




Description	
Operating Range	1880-1930 MHz
Gain	1.5 dBi
BW	50 MHz
Antenna	Wire

ANT1 GAIN $\Phi=90^\circ$




Description	
Operating Range	1880-1930 MHz
Gain	2.9 dBi
BW	50 MHz
Antenna	Wire

ANT1 GAIN $\theta=90^\circ$




Description	
Operating Range	1880-1930 MHz
Gain	-3.6 dBi
BW	50 MHz
Antenna	Wire

ANTENNA 2 LOCATION




ANT2 GAIN $\Phi=90^\circ$




Description	
Operating Range	1880-1930 MHz
Gain	4.3 dBi
BW	50 MHz
Antenna	Wire

ANT2 GAIN $\Phi=90^\circ$



Description	
Operating Range	1880-1930 MHz
Gain	3.7 dBi
BW	50 MHz
Antenna	Wire


ANT2 GAIN $\theta=90^\circ$



Description	
Operating Range	1880-1930 MHz
Gain	-3.7 dBi
BW	50 MHz
Antenna	Wire

Antenna picture

ANT 1



ANT 2

