

Dward ATCB

From: webrobot@americantcb.com
Sent: Friday, December 16, 2005 12:55 PM
To: dward@americantcb.com
Cc: whgraff@americantcb.com; murban@americantcb.com; marianne@americantcb.com
Subject: MESSAGE/NTSCalgary/TAK50200040_ATCB003022

From: Mr. Glen Moore (NTSCalgary) <mailto:glen.moore@ntscorp.com>; nick.kobrosly@ntscorp.com

Hi Dennis,

In response to your letter dated Dember 15 th and our telephone discussions regarding this application:

1. No measurement required as discussed
2. Noted, in future applications we will ensure to identify the subpart c limits as well
3. IC label - I have uploaded a corrected label with the colon inserted
4. Thank you, as per our discussion the customer will be removing the RF exposure statement from the manual
5. Internal photos - note that this device is sold to other businesses not the general public, it can be serviced by trained repair personel only. It also can only be opened using a specialized tourque wrench. Therefore the photos may be held confidential due to thier proprietary nature.
6. See point 5
7. As we discussed Doug Noble was trying to upload some of our other apps to the IC site, IC had a error which prevented the uploads. It has since been corrected, but you wont likely be able to upload until after 4:00 pm est

Thanks Dennis, if you have any further questions please do not hesitate to call