



REQUEST FOR CONFIDENTIALITY

RF Monolithics, Inc.
4441 Sigma Road
Dallas, Texas 75244 U.S.A.
Phone: (972) 233-2903
Fax Numbers:
Sales: (972) 387-8148
Accounting: (972) 233-9957
Corporate: (972) 404-9476
Human Resources: (972) 233-2051
Purchasing: (972) 233-1778

DATE 6/27/06

Equipment Autorisation Division
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

FCC ID: TE6-BTR1
Product Name: Bridge (BTR-1)

Request for Confidentiality

Pursuant to Sections 0.457 and 0.459 of the commissions rules, we hereby request that the following documents be held confidential:

- Schematics
- Block diagrams
- Technical Description

These materials contain trade secrets and proprietary information and are not customarily released to the public. The public disclosure of this information might be harmful to the company and provide unjustified benefits to our competitors.

Dated this 27 Day of June 20 06

By:


Signature

John Anthes
Printed

Title: RF Engineering Manager

On behalf of : RF Monolithics

Telephone: 972-448-3743

RF Monolithics requests confidentiality with regard to the following documents in the filing for equipment approval identified by FCC ID. No. FCC ID TE6-BTR1.



RF Monolithics, Inc.
4441 Sigma Road
Dallas, Texas 75244 U.S.A.
Phone: (972) 233-2903
Fax Numbers:
Sales: (972) 387-8148
Accounting: (972) 233-9957
Corporate: (972) 404-9476
Human Resources: (972) 233-2051
Purchasing: (972) 233-1778

- (1) Schematic diagrams
- (2) Block diagrams
- (3) Technical Description

It is the opinion of RF Monolithics disclosure of this information would result in significant loss of revenue. This information should be kept confidential for 3 years.

Authorized Signature

A handwritten signature in blue ink, appearing to read 'J. G. Cant', is written over the 'Authorized Signature' text.

RF Monolithics
4441 Sigma Rd.
Dallas, TX 75244

NOTE: Only information that is not accessible to the general public may be held confidential. Generally internal and external photos cannot be held confidentiality. The exception would be if the PC board is potted.