


-USER MANUAL



NOTE: THE MANUFACTURER IS NOT RESPONSIBLE FOR ANY RADIO OR TV INTERFERENCE CAUSED BY UNAUTHORIZED MODIFICATIONS TO THIS EQUIPMENT. SUCH MODIFICATIONS COULD VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.

Contents


The logo for Wink Communication, featuring a stylized 'W' inside a circle followed by the word 'wink' in a bold, lowercase font, with 'COMMUNICATION' in a smaller, uppercase font underneath.

ENGLISH

Wink H08 Clip Headset Overview.....	A2
Product Specification.....	A3
Getting Started.....	A3
Charging Your Headset.....	A4
Nominal Charging Time.....	A5
Talk and Standby Time.....	A5
Pairing Your Headset.....	A5
Turning Your Headset On and Off.....	A7
Using Your Headset.....	A7
Answering a Call.....	A7
Ending a Call.....	A7
Dialing from Your Mobile phone.....	A8
Voice Dialing from Your Headset.....	A8
Last Number Redialing from your Headset.....	A8
Adjusting the Volume.....	A8
Care and Maintenance	A9
Headset.....	A9
Built-in Battery.....	A10
Charging.....	A10
Safety Information.....	A10
Troubleshooting.....	A11

A1

Wink H08 Clip Headset Overview



(fig.1)

ENGLISH

A2

Product Specifications

Product Specifications

Bluetooth Specification:	Bluetooth V1.1	Range of Frequency:	2.4GHz-2.48GHz
Headset Dimensions:	52x26x27 mm	Box Dimensions:	170x132x55 mm
Nominal Charging Time:	3 Hours	Talk Time:	Up to 4.5 Hours
Standby Time:	Up to 150 Hours	Weight:	21 grams

***May vary due to users' operation mode and mobile phone settings**

Getting Started

To use your Wink H08 Clip Headset (The headset), please follow these following steps:

Charge your headset

Pair your headset with a Bluetooth-enabled mobile phone




(fig.2)

ENGLISH

A3

Charging your Headset

The Headset comes with a built-in rechargeable battery. Prior to using the headset, it is recommendable to charge the battery fully for the first time. Connect the charger to an AC wall outlet and the charger plug to the headset's charging socket (fig.1). The **LED** will be red while charging and will turn to be blue after being fully charged.



IMPORTANT Charging indication will be delayed for about 40 minutes if the headset has not been used for a long time or the battery is drained.

A4

Nominal Charging Time


Charging the battery fully is normally within 4 hours. When the battery is fully charged, the **LED** will turn blue. Disconnect the charger from AC wall outlet and the headset, press and hold the MFB (fig.2) for 3 seconds to turn the headset on. Please refer to "Turning Your Headset On and Off" on page 7.

Talk & Standby Time

The fully charged battery offers up to 4.5 hours talk time and up to 150 hours standby time. When no calls are in progress, the headset remains turned on in standby mode.

Pairing Your Headset

Prior to using the Headset for the first time, you must pair it with a Bluetooth-enabled mobile phones. The information on the next page describes pairing instructions for a typical Bluetooth-enabled mobile phones. Headset pairing procedures are subject to different models of mobile phones.



(fig.4)

Pairing Your Headset

1. Place the headset and the mobile phone where they are easily viewable by no more than 1 meter apart.
2. Ensure the headset is OFF.
3. Press and hold the MFB(S1) until the headset **LED** alternately flashes blue and red.
4. Activate your mobile phone's bluetooth function by referring to your mobile phone user guide for details.
5. Set the mobile phone to search for Bluetooth devices within about 1 meter as instructed in the mobile phone's guide and select Wink H08 from the list.
6. Enter the preprogrammed passkey "1234" and press "OK" to pair your headset and mobile phone. When the pairing is complete, the headset **LED** will flash blue rapidly for 3 times.
7. Go back to your mobile handset's main menu, for certain mobile phone models, a headset icon will be shown on the screen. You should now be able to make and receive calls using your headset.

IMPORTANT if the pairing cannot be completed within 2 minutes while the pairing mode is activated, the headset **LED** flashes blue red with 1 beeps and the headset will go back to stand by mode. Please repeat Steps 2 to 6 to pair the headset and the mobile phone again.

A6

Turning Your Headset On and Off

Turning Your Headset

Press and hold the MFB(S1) for 5 seconds until you hear two short beeps. The LED will flash blue.

IMPORTANT Press the MFB(S1) again each time you turn on the headset to reactivate pairing so that the connection between the headset and the mobile phone is resumed. For pairing, please refer to "pairing Your Headset" on the last page.

Turning Off the Headset

Press the MFB(S1) for 1 second, you hear a beep, hold it to 3 seconds until you hear 2 beeps, the LED flash stops.

Using Your Headset

Answering Call

To answer a call, when you hear your phone or headset ring, press the MFB(S1) to accept the call via your mobile phone in the normal way.

Ending Call

Press the MFB(S1) to end your call or end the call via your mobile phone in the normal way.

A7

Dialing from Your Mobile Phone

Simply make calls on your mobile phone in the normal way.

Voice Dialing from Your Headset

If your mobile phone is equipped with a voice dialing function, simply press the MFB(S1) on your headset and when hear a beep, say the voice tag.

IMPORTANT Please make sure to record voice tag into the mobile phone first before using voice dialing function.

Last phone Number re-dialing

When the headset is in standby state, slightly press the Volume Adjusting key for 5 seconds, it can redial the last phone number.

IMPORTANT The above functions are only applicable to mobile phones with bluetooth handsfree profile. Functionality varies depending on the mobile phone model you have. Please refer to your mobile phone user guide for additional information.

Adjusting the Volume

S2 is volume increasing key, while S3 is decreasing key. Press the Volume Key repeatedly until you reach the desired volume level.

Care and Maintenance

Headset

Do not Consider turning your headset off before placing it in your pocket or bag .

If the MFB(S1) is accidentally depressed, your mobile phone may place an unintended call.

Do not expose the headset to liquid, moisture or humidity as it is not waterproof.

Do not use abrasive cleaning solvents to clean the headset.

Do not put the headset in a extremely high or low temperature place.

Do not expose of the headset in a fire as it will result in an explosion.

Do not expose your headset to contact with sharp objects as this will cause scratches and damage.

Do not stick anything inside the headset as this may damage internal components.

Do not attempt to disassemble the headset as it does not contain serviceable components.

If you do not use the headset for long periods, be sure to store it in a dry place, free from extreme temperatures and dust.

Dispose of battery according to local regulations. Do not dispose as household waste.

Built-in Battery

Do not attempt to replace the headset's battery yourself as it is in-built and is not changeable.
Charge the battery in accordance with the instruction supplied with this user guide.
Only use the manufacturer supplied charger when charging the headset.

Charging

Only use the manufacturer supplied charger when charging the headset.
Charging indication will be delayed for about 40 minutes if the headset has not been used for a long time (more than one month) or the battery is drained.
Do not disassemble the charger as it may expose you to dangerous voltages or other risks.
Incorrect disassemble can cause electric shock when the headset is subsequently used.
Do not use the charger outdoors or in damp areas.
Only charge the headset's built-in battery in accordance with the instructions of this user guide. Avoid charging the headset in extremely high or low temperatures.

Safety Information

Safety Information

Check local laws regarding use of a mobile phone and headset while driving. If you use the headset while driving, ensure your attention and focus remains on your responsibility of driving safely. Never allow children to play with the headset-small parts may be a choking hazard. Observe all signs that require an electrical device or RF radio product to be switched off in designated areas. These could include hospitals, blasting areas, and potentially explosive atmospheres. Turn off your headset prior to boarding an aircraft. Do not use your headset in an aircraft. Never mount or store your headset over any air bag deployment area as serious injury may result when an air bag deploys. Do not open or mutilate the built-in battery.