








Report No.: AAEMT/RF/250131-01-03




802.11be80

Channel 135: 6625MHz





Date: 17.MAR.2025 23:40:07



Date: 20.MAR.2025 00:17:34


Report No.: AAEMT/RF/250131-01-03






802.11be160

Channel 143: 6665MHz




Date: 18.MAR.2025 00:04:53




Date: 20.MAR.2025 00:29:53

802.11ax20


Channel 189: 6895MHz




Date: 19.MAR.2025 19:33:29





Date: 19.MAR.2025 21:15:27







802.11ax40

Channel 195: 6925MHz




Report No.: AAEMT/RF/250131-01-03






802.11ax80

Channel 199: 6945MHz




Date: 19.MAR.2025 18:18:48




Date: 19.MAR.2025 21:42:36

802.11ax160

Channel 207: 6985MHz





Date: 19.MAR.2025 18:18:48




Date: 19.MAR.2025 21:48:34


802.11be20


Channel 189: 6895MHz




Report No.: AAEMT/RF/250131-01-03









Report No.: AAEMT/RF/250131-01-03





Report No.: AAEMT/RF/250131-01-03






802.11be160

Channel 207: 6985MHz




Report No.: AAEMT/RF/250131-01-03

Antenna 1:




802.11ax20


Channel 45: 6175MHz



Date: 19.MAR.2025 00:38:41




Date: 19.MAR.2025 23:08:02




Report No.: AAEMT/RF/250131-01-03

802.11ax40


Channel 3: 5965MHz




Date: 19.MAR.2025 17:26:49




Date: 19.MAR.2025 21:02:40




Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03






802.11ax160


Channel 15: 6025MHz





Date: 19.MAR.2025 18:07:38




Date: 19.MAR.2025 22:18:22








Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03

802.11be40


Channel 3: 5965MHz




Date: 18.MAR.2025 22:45:03



Date: 20.MAR.2025 17:36:38





Report No.: AAEMT/RF/250131-01-03




802.11be80


Channel 7: 5985MHz



Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




802.11be160

Channel 15: 6025MHz




Date: 18.MAR.2025 00:22:07




Date: 20.MAR.2025 18:23:38

Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03

802.11be320

Channel 63: 6265MHz




Date: 18.MAR.2025 00:17:27




Date: 20.MAR.2025 18:28:50

802.11ax20

Channel 97: 6435MHz




Date: 19.MAR.2025 00:42:32




Date: 19.MAR.2025 23:11:24

802.11ax20

Channel 105: 6475MHz




Date: 19.MAR.2025 17:09:11




Date: 19.MAR.2025 23:14:14

Report No.: AAEMT/RF/250131-01-03




802.11ax40

Channel 99: 6445MHz



Date: 19.MAR.2025 17:31:30



Date: 19.MAR.2025 22:39:20