




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 165




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax20

Channel: 149




Channel: 157





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 165




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11n40



Channel: 38





Channel: 46



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be40

Channel: 38




Channel: 46




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11n40


Channel: 54



Channel: 62



Report No.: AAEMT/RF/250131-01-02






99% OBW 802.11ax40

Channel: 54



Channel: 62






Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11n40


Channel: 102





Channel: 110



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 134




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

Channel: 134




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be40

Channel: 102




Channel: 110



Report No.: AAEMT/RF/250131-01-02

Channel: 134




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac40

Channel: 151




Channel: 159




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax40

Channel: 151




Channel: 159




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be40

Channel: 151




Channel: 159



Report No.: AAEMT/RF/250131-01-02


99% OBW 802.11ac80

Channel: 42




99% OBW 802.11ax80



Channel: 42




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac80



Channel: 106



Channel: 122




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be80



Channel: 106




Channel: 122





Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02





MRU Antenna 0:





Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

Channel: 122



802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX





802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

26dB 802.11be EHT160_Nss1,(MCS0),RU484+RU484 MRU 1_2TX




Report No.: AAEMT/RF/250131-01-02

Channel: 42



99% OBW 802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX





99% OBW 802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 122



99% OBW 802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX





99% OBW 802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX




Report No.: AAEMT/RF/250131-01-02






Report No.: AAEMT/RF/250131-01-02




Antenna 1:





Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 48




26dB BW 802.11ac20

Channel: 36

Report No.: AAEMT/RF/250131-01-02




Channel: 40




Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02

26dB BW 802.11be20


Channel: 36



Channel: 40



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 64




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 64




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 64




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 64




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 64




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02

26dB BW 802.11be20

Channel: 100




Channel: 116




Report No.: AAEMT/RF/250131-01-02

Channel: 140



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 165




Report No.: AAEMT/RF/250131-01-02

6dB BW 802.11n20

Channel: 149




Channel: 157





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 165



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

26dB BW 802.11ac40

Channel: 38



Channel: 46

