





Report No.: AAEMT/RF/250131-01-02

be40 5.755 GHz





Report No.: AAEMT/RF/250131-01-02

be40 5.795 GHz



Report No.: AAEMT/RF/250131-01-02

be80 5.775 GHz




Report No.: AAEMT/RF/250131-01-02

MRU Antenna 0:


be80 5.210 GHz

802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX



Report No.: AAEMT/RF/250131-01-02


802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02



be80 5.290 GHz

802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX



Report No.: AAEMT/RF/250131-01-02



802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02



be80 5.530 GHz

802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX



Report No.: AAEMT/RF/250131-01-02



802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02


be80 5.610 GHz

802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX



Report No.: AAEMT/RF/250131-01-02


802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02


be160 5.570 GHz

802.11be EHT160_Nss1,(MCS0),RU996+RU484 MRU 2_2TX




Report No.: AAEMT/RF/250131-01-02

802.11be EHT160_Nss1,(MCS0),RU484+3xRU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02


802.11be EHT160_Nss1,(MCS0),RU484+RU484 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02



be80 5.775 GHz

802.11be EHT80_Nss1,(MCS0),RU484+RU242 MRU 3_2TX



Report No.: AAEMT/RF/250131-01-02


802.11be EHT80_Nss1,(MCS0),RU242+RU242 MRU 1_2TX



Report No.: AAEMT/RF/250131-01-02



Antenna 1:

a20 5.180 GHz





Report No.: AAEMT/RF/250131-01-02

a20 5.240 GHz





Report No.: AAEMT/RF/250131-01-02

n20 5.180 GHz





Report No.: AAEMT/RF/250131-01-02

n20 5.240 GHz





Report No.: AAEMT/RF/250131-01-02

n40 5.190 GHz





Report No.: AAEMT/RF/250131-01-02

n40 5.230 GHz





Report No.: AAEMT/RF/250131-01-02

ac20 5.180 GHz




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

ac40 5.190 GHz




Report No.: AAEMT/RF/250131-01-02

ac40 5.230 GHz





Report No.: AAEMT/RF/250131-01-02

ac80 5.210 GHz




Report No.: AAEMT/RF/250131-01-02

ax20 5.180 GHz





Report No.: AAEMT/RF/250131-01-02

ax20 5.240 GHz





ax40 5.190 GHz





Report No.: AAEMT/RF/250131-01-02

ax40 5.230 GHz





Report No.: AAEMT/RF/250131-01-02

ax80 5.210 GHz





Report No.: AAEMT/RF/250131-01-02

be20 5.180 GHz





Report No.: AAEMT/RF/250131-01-02

be20 5.240 GHz




Report No.: AAEMT/RF/250131-01-02

be40 5.190 GHz




Report No.: AAEMT/RF/250131-01-02

be40 5.230 GHz





Report No.: AAEMT/RF/250131-01-02

be80 5.210 GHz





Report No.: AAEMT/RF/250131-01-02

a20 5.260 GHz





Report No.: AAEMT/RF/250131-01-02

a20 5.320 GHz





Report No.: AAEMT/RF/250131-01-02

n20 5.260 GHz





Report No.: AAEMT/RF/250131-01-02

n20 5.320 GHz





Report No.: AAEMT/RF/250131-01-02

n40 5.270 GHz





Report No.: AAEMT/RF/250131-01-02

n40 5.310 GHz





Report No.: AAEMT/RF/250131-01-02

ac20 5.260 GHz





Report No.: AAEMT/RF/250131-01-02

ac20 5.320 GHz





Report No.: AAEMT/RF/250131-01-02

ac40 5.270 GHz





Report No.: AAEMT/RF/250131-01-02

ac40 5.310 GHz



Report No.: AAEMT/RF/250131-01-02

ac80 5.290 GHz



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

ax20 5.320 GHz

