



**FCC External Photographs
for**

TempSens

[FCC ID: TS4 – TWS-049]

model

TWS-049 - Sensor

report number

20051019-01-Fc15

manufacturer

**Tehama Wireless Design Group
423 Tehama Street
San Francisco, California, 94103**

judgement

Complies

tests and report by

**ITC Engineering Services, Inc. (ITC)
9959 Calaveras Road, P.O. Box 543
Sunol, California 94586**

Tel.: (925) 862-2944

Fax: (925) 862-9013

E-Mail: docs@itcemc.com

Web Site: www.itcemc.com



Lab Code: 200172-0

**EN45001 Accredited Compliance Laboratory (RES-GmbH)
Registration number: TTI-P-G 159/98-00 (RES-GmbH)**

Table of Contents

PART 1	GENERAL	3
Section 1.1	General Information	3
Section 1.2	Tests Performed:	3
PART 2	EXTERNAL PHOTOGRAPHS	4

List of Figures

Figure 1: EUT External View (Top)	4
Figure 2: EUT External View (Bottom)	4
Figure 3: EUT Component View 1	5

PART 1 GENERAL

SECTION 1.1 GENERAL INFORMATION

Product Type Model(s)	TempSens TWS-049 - Sensor	
Manufacturer's Name Manufacturer's Address Country Telephone and Fax Contact and Email	Tehama Wireless Design Group. 423 Tehama Street San Francisco, California 94103 USA Tel: +1 (415) 495-7344 Mr. Jim Orton	Fax: +1 (415) 495-7314 orton@tehamawireless.com
Test Laboratory	ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543 Sunol, CA 94586-0543 Email: docs@itcemc.com Web Site: http://www.itcemc.com	Tel: +1(925) 862-2944 Fax: +1(925) 862-9013
Test Number and Report Numbers	20051019-01	20051019-01-Fc15
Test Date(s) & Issue Date	Oct. 27 th - Nov. 2 nd of 2005	November 11 th , 2005
Test Engineer(s)	Femi Ojo and Lan Vu	
Chief Engineer	Michael Gbadebo, P.E	
Documentation	George W Brown II.	
Test Results	☒ Complies as Tested	☐ Fail

SECTION 1.2 TESTS PERFORMED:

FCC Rules and Regulations per 47 CFR 15.247

PART 2 EXTERNAL PHOTOGRAPHS



Figure 1: EUT External View (Top)



Figure 2: EUT External View (Bottom)




Figure 3: EUT Component View 1