


Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

4.502 GHz
+4dBm
Harry

1.418 GHz
1.560 GHz
Harry




Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

4.502 GHz
+4dBm
Harry

1.418 GHz
1.560 GHz
Harry




Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

1.430 GHz
1.567 GHz
Sally

4.502 GHz
+0.5 dBm
Sally




Company:
FCC ID:

Huber+Suhner AG
TTDSL60100


1.430 GHz
1.567 GHz
Sally

4.502 GHz
+0.5 dBm
Sally



Company:
FCC ID:

Huber+Suhner AG
TTDSL60100




Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

4.502 GHz
+ 4dBm
Clyde

1.425 GHz
1.576 GHz
Clyde




Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

1.426 GHz
1.566 GHz
Bonnie

4.502 GHz
+1.2 dBm
Bonnie




Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

1.426 GHz
1.566 GHz
Bonnie

4.502 GHz
+1.2 dBm
Bonnie



Company:
FCC ID:

Huber+Suhner AG
TTDSL60100

4.502 GHz
+ 4 dBm
Clyde

1.425 GHz
1.576 GHz
Clyde

