

Tranzeo EMC Labs Inc.
19473 Fraser Way
Pitt Meadows, BC
Canada V3Y 2V4

Unity Wireless Systems Corp.
Osprey 35 W CDMA SCPA
100.0188.001
Power Amplifier
Label Location

March 23, 2006

Report Number: TRL230306.1



Bruce Balston, EMC Engineer



Andrew Marles, EMC Coordinator

C.1 FCC Label location




Figure 1 – External back panel, FCC Label location..