



13 June 2006

To whom it may concern:

We the undersigned, seek FCC and IC approval of a Class II Permissive Change for our Speedway RFID Reader, Impinj model number IPJ-R1000. The primary reason for the Class II change is the replacement of a component in the RF transmit path in order to obtain a RoHS (lead-free) PCB assembly. The original component will not be available in a RoHS version. The nature of this change necessitates the need for RF testing to verify that the reader remains compliant.

Additional changes were made to support enhanced software functionality and future reuse of the PCB for other regions. All design changes are summarized in the word document entitled *Speedway_Design_Change_Description*.

FCC certification number: TWYIPJR1000

IC certification number: 6324A-IPJR1000

Sincerely,

William Ashley
Vice President, RFID Reader Products
Impinj, Inc.

Impinj, Inc.
701 N. 34th Street,
Suite 300
Seattle, WA 98103

Tel (206) 517-5300
Fax (206) 517-5262

www.impinj.com