



INTERTEK TESTING SERVICE

Report No.: 0600342

Equipment Photographs

Model : T557

(Internal)





FCC ID: TX7T557

Equipment Photographs

Model : T557

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0600342

Equipment Photographs

Model : T557



(Internal)



Equipment Photographs

Model : T557



(Internal)



Equipment Photographs

Model : T557



(Internal)



Equipment Photographs

Model : T557

(Internal)




INTERTEK TESTING SERVICE

Report No.: 0600342

Equipment Photographs

Model : T557



(Internal)



Equipment Photographs

Model : T557

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0600342

Equipment Photographs

Model : T557

(Internal)



FCC ID: TX7T557



INTERTEK TESTING SERVICE

Report No.: 0600342

Equipment Photographs

Model : T557


(Internal)



Equipment Photographs

Model : T557

(Internal)




INTERTEK TESTING SERVICE

Report No.: 0600342

Equipment Photographs

Model : T557

(Internal)



Equipment Photographs

Model : T557

(Internal)

