



Report No.: 0601332
DVD Playing mode
(Modulating On)
AC Mains


Tested By:Hong, Report No.:0601332

Scan Settings (1 Range)

Frequencies				Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
1 15 9k	30M	EW0090	
21 9k	30M	EW0698	



Report No.: 0601332
DVD Playing mode
(Modulating On)
AC Mains

Tested By: Hong, Report No.: 0601332

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

0.15000 41.6 66.0

Frequency AV Level AV Limit

MHz dBuV dBuV

no Results

* limit exceeded

Ctrl No.: