

Correspondence by Project

Project Number:

1348586678

Correspondence Number	Memo
TZXRS100-1	1) The test report has a different FCC ID listed then what is listed in the application. Please explain. Response: The Test Report has been Revised to include the correct FCC ID. 2) The test report states that the device was both transmitting and receiving, but no data supporting the receive mode was supplied. Please submit the data for the receive mode. Response: The EUT has no receive mode as the chip (TXM-433-LR-S) is a transmit chip only. The test report has been revised to show this. 3) The operational description submitted does not meet the operational requirements of 15.231(a). Please explain how the device will meet the operational requirements of 15.231(a). Response: The Operational Description has been revised. 4) In the FCC statement located in the User Manual, it mentions that the device was certified to comply with the limits of a class B computing device, which is incorrect. Please correct and send a corrected user manual. Response: The Users Manual has been revised. 5) In the FCC statement located in the User Manual, it mentions that the device requires shielded cables to maintain compliance, which is incorrect. Please correct and send a corrected user manual. Response: The Users Manual has been revised.