


Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5580MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		





Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5745MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)			3





Audix Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,


New Taipei City244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303

Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5825MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)			3





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5190MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5230MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5270MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5310MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5510MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		



