


8. PHOTOGRAPHS OF MEASUREMENT



Note : EUT: Slave; Master: AP

