



Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5500MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5600MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5700MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	3		



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			3






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
		Frequency	TX 5190MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


20GHz – 25GHz




25GHz – 30GHz



30GHz – 35GHz




35GHz – 40GHz




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	I
		Frequency	TX 5230MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	






Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
		Frequency	TX 5270MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2A
		Frequency	TX 5310MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	






Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5510MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


20GHz – 25GHz




25GHz – 30GHz



30GHz – 35GHz




35GHz – 40GHz



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5590MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		3	





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303





Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5670MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	





Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	III
		Frequency	TX 5755MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	






Audix Technology Corp.

No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303


Test Date	2017/09/26	Temp./Hum.	25°C/55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5795MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


15GHz – 20GHz




20GHz – 25GHz




25GHz – 30GHz



30GHz – 35GHz





35GHz – 40GHz




Antenna: Omni-S Antenna


Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		





Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
		Frequency	TX 5200MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	I
		Frequency	TX 5240MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		






Test Date	2017/09/25	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


20GHz – 25GHz




25GHz – 30GHz



30GHz – 35GHz




35GHz – 40GHz




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/09/25	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/09/25	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5320MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		0	





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303





Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5500MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0	







Test Date	2017/10/02	Temp./Hum.	25°C/54 ~ 55%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5600MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0	





Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		






Audix Technology Corp.

No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301

Fax: +886 2 26099303


Test Date	2017/09/25 ~ 10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0



15GHz – 20GHz




20GHz – 25GHz




25GHz – 30GHz



30GHz – 35GHz



35GHz – 40GHz




Audix Technology Corp.


No. 53-11, Dingfui, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	4.2dB	Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0	





Test Date	2017/10/02	Temp./Hum.	25°C/55%
Mode	802.11a	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


15GHz – 20GHz



20GHz – 25GHz



25GHz – 30GHz



30GHz – 35GHz



35GHz – 40GHz

