



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0		





Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02 ~ 06	Temp./Hum.	24°C/54 ~ 55%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5600MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		





Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C/54 ~ 55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		





Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C/54 ~ 55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5190MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5230MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5270MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5310MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5510MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5590MHz
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0		







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5670MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		





Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C/54 ~ 55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5755MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0





Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C/54 ~ 55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5795MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0

