




11A-MIMO_Ant0_6435




11A-MIMO_Ant1_6435




11A-MIMO_Ant0_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A-MIMO_Ant1_6475




11A-MIMO_Ant0_6515




11A-MIMO_Ant1_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A-MIMO_Ant0_6535




11A-MIMO_Ant1_6535




11A-MIMO_Ant0_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A-MIMO_Ant1_6715




11A-MIMO_Ant0_6855




11A-MIMO_Ant1_6855


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A-MIMO_Ant0_6875




11A-MIMO_Ant1_6875




11A-MIMO_Ant0_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11A-MIMO_Ant1_7015




11A-MIMO_Ant0_7115




11A-MIMO_Ant1_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5955




11AX20MIMO_Ant1_5955




11AX20MIMO_Ant0_6175


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6175




11AX20MIMO_Ant0_6415




11AX20MIMO_Ant1_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6435




11AX20MIMO_Ant1_6435




11AX20MIMO_Ant0_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6475




11AX20MIMO_Ant0_6515




11AX20MIMO_Ant1_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6535




11AX20MIMO_Ant1_6535




11AX20MIMO_Ant0_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6715




11AX20MIMO_Ant0_6855




11AX20MIMO_Ant1_6855


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6875




11AX20MIMO_Ant1_6875




11AX20MIMO_Ant0_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_7015




11AX20MIMO_Ant0_7115




11AX20MIMO_Ant1_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_5965




11AX40MIMO_Ant1_5965




11AX40MIMO_Ant0_6165


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6165




11AX40MIMO_Ant0_6405




11AX40MIMO_Ant1_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_6445




11AX40MIMO_Ant1_6445




11AX40MIMO_Ant0_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6485




11AX40MIMO_Ant0_6525




11AX40MIMO_Ant1_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_6565




11AX40MIMO_Ant1_6565




11AX40MIMO_Ant0_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6725




11AX40MIMO_Ant0_6845




11AX40MIMO_Ant1_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_6885




11AX40MIMO_Ant1_6885




11AX40MIMO_Ant0_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_7005



11AX40MIMO_Ant0_7085



11AX40MIMO_Ant1_7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.