




11AX40MIMO_Ant0_6445




11AX40MIMO_Ant1_6445




11AX40MIMO_Ant0_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6485




11AX40MIMO_Ant0_6525




11AX40MIMO_Ant1_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_6565




11AX40MIMO_Ant1_6565




11AX40MIMO_Ant0_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6725




11AX40MIMO_Ant0_6845




11AX40MIMO_Ant1_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_6885




11AX40MIMO_Ant1_6885




11AX40MIMO_Ant0_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_7005




11AX40MIMO_Ant0_7085




11AX40MIMO_Ant1_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_5985




11AX80MIMO_Ant1_5985




11AX80MIMO_Ant0_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145




11AX80MIMO_Ant0_6385




11AX80MIMO_Ant1_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_6465




11AX80MIMO_Ant1_6465




11AX80MIMO_Ant0_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6545




11AX80MIMO_Ant0_6705




11AX80MIMO_Ant1_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_6785




11AX80MIMO_Ant1_6785




11AX80MIMO_Ant0_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6865




11AX80MIMO_Ant0_6945




11AX80MIMO_Ant1_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_7025




11AX80MIMO_Ant1_7025




11AX160MIMO_Ant0_6025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6025




11AX160MIMO_Ant0_6185




11AX160MIMO_Ant1_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant0_6345




11AX160MIMO_Ant1_6345




11AX160MIMO_Ant0_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6505




11AX160MIMO_Ant0_6665




11AX160MIMO_Ant1_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant0_6825




11AX160MIMO_Ant1_6825




11AX160MIMO_Ant0_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6985




11AX20MIMO_Ant0_5955_26Tone_RU0




11AX20MIMO_Ant0_5955_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5955_106Tone_RU53



11AX20MIMO_Ant1_5955_26Tone_RU0



11AX20MIMO_Ant1_5955_52Tone_RU37

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.