




11AX20MIMO_Ant1_5955_106Tone_RU53




11AX20MIMO_Ant0_6175_26Tone_RU4




11AX20MIMO_Ant0_6175_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6175_106Tone_RU53




11AX20MIMO_Ant1_6175_26Tone_RU4




11AX20MIMO_Ant1_6175_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6175_106Tone_RU53




11AX20MIMO_Ant0_6415_26Tone_RU8




11AX20MIMO_Ant0_6415_52Tone_RU40


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6415_106Tone_RU54




11AX20MIMO_Ant1_6415_26Tone_RU8




11AX20MIMO_Ant1_6415_52Tone_RU40


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6415_106Tone_RU54




11AX20MIMO_Ant0_6435_26Tone_RU0




11AX20MIMO_Ant0_6435_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6435_106Tone_RU53




11AX20MIMO_Ant1_6435_26Tone_RU0




11AX20MIMO_Ant1_6435_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6435_106Tone_RU53




11AX20MIMO_Ant0_6475_26Tone_RU4




11AX20MIMO_Ant0_6475_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6475_106Tone_RU53




11AX20MIMO_Ant1_6475_26Tone_RU4




11AX20MIMO_Ant1_6475_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6475_106Tone_RU53




11AX20MIMO_Ant0_6515_26Tone_RU8




11AX20MIMO_Ant0_6515_52Tone_RU40


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6515_106Tone_RU54




11AX20MIMO_Ant1_6515_26Tone_RU8




11AX20MIMO_Ant1_6515_52Tone_RU40


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6515_106Tone_RU54




11AX20MIMO_Ant0_6535_26Tone_RU0




11AX20MIMO_Ant0_6535_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6535_106Tone_RU53




11AX20MIMO_Ant1_6535_26Tone_RU0




11AX20MIMO_Ant1_6535_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6535_106Tone_RU53




11AX20MIMO_Ant0_6715_26Tone_RU4




11AX20MIMO_Ant0_6715_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6715_106Tone_RU53




11AX20MIMO_Ant1_6715_26Tone_RU4




11AX20MIMO_Ant1_6715_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6715_106Tone_RU53




11AX20MIMO_Ant0_6855_26Tone_RU8




11AX20MIMO_Ant0_6855_52Tone_RU40


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6855_106Tone_RU54




11AX20MIMO_Ant1_6855_26Tone_RU8




11AX20MIMO_Ant1_6855_52Tone_RU40


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6855_106Tone_RU54




11AX20MIMO_Ant0_6875_26Tone_RU0




11AX20MIMO_Ant0_6875_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_6875_106Tone_RU53




11AX20MIMO_Ant1_6875_26Tone_RU0




11AX20MIMO_Ant1_6875_52Tone_RU37


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6875_106Tone_RU53




11AX20MIMO_Ant0_7015_26Tone_RU4




11AX20MIMO_Ant0_7015_52Tone_RU38


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_7015_106Tone_RU53



11AX20MIMO_Ant1_7015_26Tone_RU4



11AX20MIMO_Ant1_7015_52Tone_RU38

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.