



View of Inside




Report no. ETLE061201.547, Page D1 of D3

Top side view of main board



Bottom side view of main board



Report no. ETLE061201.547, Page D3 of D3