


Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



RADIATED EMISSIONS TEST SETUP / FRONT VIEW

Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



RADIATED EMISSIONS TEST SETUP / REAR VIEW

Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



CONDUCTED EMISSIONS TEST SETUP / FRONT VIEW

Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



CONDUCTED EMISSIONS TEST SETUP / REAR VIEW

Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



EXTREME CONDITIONS 1

Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



EXTREME CONDITIONS 2

Company: Tyco Healthcare / Mallinckrodt
Model Tested: 844003
FCC ID: UEI844003
Canada ID: 3502A-844003



EXTREME CONDITIONS 3