

10. SETUP PHOTOS

RADIATED MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)



FRONT PHOTO




BACK PHOTO



RADIATED RF MEASUREMENT SETUP >1GHz




RADIATED EMISSION 18-26 GHz



RADIATED EMISSION 26 -40 GHz




FREQUENCY STABILITY SETUP




POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP FOR ADAPTER 1

LINE CONDUCTED FRONT PHOTO




LINE CONDUCTED BACK PHOTO




POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP FOR ADAPTER 2

LINE CONDUCTED FRONT PHOTO



LINE CONDUCTED BACK PHOTO



END OF REPORT