Model/Modelo: P90D25AL-HP7(L2)
Household Microwave Oven (Not for commercial use)
Input 120V, 60Hz, single phase 1350W
Output 900W, 2450MHz
Made in CHINA

FCC ID: UHW9037
Serial NO: XGC2900828
Manufacture Date:July, 2023
This ISM device complies with Canadian CAN ICES-001 (B)/NMB-001 (B)
Questions? Call 1- 800 - 807 - 6777

Energy Verified
Rendement Énergétique Vérifié

Four à micro-ondes (pour usage domestique seulement)
Non destiné à être encastré
Alimentation 120V, 60Hz, memophasé 1350W
Puissance de sortie 900W, 2450MHz
Fabriqué en China
Date de fabrication: Juillet, 2023
Cet appareil ISM conforme à la norme ICES-001 du Canada. CAN ICES-001 (B)/NMB-001 (B)

c UL LISTED
(MICROWAVE OVEN)
(FOUR À MICRO-ONDES)
<23FJ>
E61582

WARNING

Electrical Shock Hazard
Disconnect power before servicing.
Replace all parts and panels before operating.
Failure to do so can result in death or electric shock .

PRECAUTIONS FOR SAFE USE TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY. DO NOT ATTEMPT TO OPERATE THE OVEN WITH:
- OBJECT CAUGHT IN DOOR.
- DOOR THAT DOES NOT CLOSE PROPERLY.
- DAMAGED DOOR, HINGE, LATCH, OR SEALING SURFACE.

THIS OVEN COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS, 21 CFR SUBCHAPTER J. MICROWAVE FREQUENCY: 2450MHz

DO NOT ATTEMPT TO OPERATE THIS MICROWAVE OVEN WITH:
(A) OBJECT CAUGHT IN DOOR
(B) DOOR THAT DOES NOT CLOSE PROPERLY
(C) DAMAGED DOOR HINGE, LATCH OR SEALING SURFACE
(D) MEAT PROBE CAUGHT IN DOOR (if applicable)

CALIFORNIA RESIDENTS ONLY - WARNING:
Cancer and Reproductive Harm – www.P65Warnings.ca.gov

AVERTISSEMENT

Risque de choc électrique
Déconnecter la source de courant électrique avant l' entretien. Replacer pièces et panneaux avant de faire la remise en marche.
Le non-respect de ces instructions peut causer un décès ou un choc électrique

PRÉCAUTIONS À PRENDRE POUR UNEUTILISATIONSÉCURITAIREETÉVITERUNE EXPOSITION EXCESSIVE À L'ÉNERGIE DEGAGE PAR L'APPAREIL. NE PAS UTILIZER L'APPAREILSI
-UN OBJET BLOQUE LA FERMETURE DE PORTE
-SI LA PORTE NE SE FERME PAS HERMÉTIQUEMENT
-SI LA PORTE, LA POIGNÉEOU LE LOQUETESTENDOMMAGÉ ET QUEL'INTÉRIEURN'EST PAS COMPLÈTEMENTÉTANCHE.

CE FOUR ESTCONFORMEAUX STANDARDS DE LA NORME AMÉRICAINE DE PERFORMANCE DHHS, 21 CFR SUBCHAPER FRÉQUENCE ÉMISE DE 2450MHz

NE PAS UTILISER CE FOUR SI:
(A) UN OBJECT BLOQUE L'OUVERTURE DE LA PORTE.
(B) LA PORTE NE FERME PAS BIEN.
(C) LES CHARNIERES, LE VERROUILLAGE OU LE JOINT D'ETANCHEITE SONT ENDOMMAGES.
(D) LA SONDE DU THERMOMETRE A VIANDE BLOQUE LA PORTE (lorsqu il y en a une)

RESIDENTS DE CALIFORNIES EULEMENT –ADVERTISS EMENT:
Cancer et troubles de la reproduction – www.P65Warnings.ca.gov