




1 Peak Power Measurement with Meter



2 Peak Power Spectral Density (UNII-1 Band)



3 Peak Excursion (UNII-1 Band)