

Changes in the Aprisa SR+ 896 MHz

Revision 1

Alan Turner

October 23, 2025

Changes in the Aprisa SR+ 896 MHz associated with the change to the transmitter and receiver synthesizers under C2PCPX. Changes required due to the obsolescence of the original synthesizer component. No additional functionality has been added with this change.

Both transmitter and receiver synthesizers are located on the bottom of the Printed Circuit Assembly (PCA), however top layouts and photographs have been included for completeness.

FCC ID:	UIPSQ896M141
ISED Radio Cert. No.:	6772A-SQ896M141
HVIN:	SQ896M141



Figure 1: Old PCA layout top view	2
Figure 2: Old PCA photo top view	2
Figure 3: Old PCA layout bottom view	3
Figure 4: Old PCA Photo bottom view	3
Figure 5: New PCA layout top view	4
Figure 6: New PCA photo top view	4
Figure 7: New PCA layout bottom view	5
Figure 8: New PCA photo bottom view (changed areas highlighted)	5
Figure 9: Old TX synthesizer schematic.....	6
Figure 10: Old RX synthesizer schematic.....	7
Figure 11: New TX synthesizer schematic	8
Figure 12: New RX synthesizer schematic	9





Figure 2: Old PCA photo top view




Figure 3: Old PCA layout bottom view




Figure 4: Old PCA Photo bottom view




Figure 5: New PCA layout top view




Figure 6: New PCA photo top view




Figure 7: New PCA layout bottom view




Figure 8: New PCA photo bottom view (changed areas highlighted)