




Datecode=Bxxxxxxx			
	Sensor -90	Sensor 0	Sensor +90
J31H	X	0	X
J31L	0	X	10nF

Datecode=FWGExxxxx			
	Sensor +90	Sensor 0	Sensor -180
J31H	X	0	X
J31L	0	X	10nF

	BME	WCD/R	FWGER
R20	open	open	short
motion wake up	no have	no have	have