

**I-ROCKS TECHNOLOGY CO., LTD**  
**ZIP 231, 12F, NO.190, CHUNG-HSIN RD., SEC.2, HSIN-TIEN CITY, TAIPEI**  
**COUNTRY, TAIWAN, R.O.C.**  
**TEL: 886-2-2911-3080 FAX: 886-2-2914-1712**

Date: 2016.04.28

Equipment Authorization Division  
Office of Engineering and Technology  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Dear Sirs:

I-ROCKS TECHNOLOGY CO., LTD requests acceptance of the labeling proposal described below for IRM13R bearing FCC identifier UJ9IRM13R.

The subject IRM13R models as shown in figure 1, authorized under FCC Part 15 Subpart C




figure 1

**I-ROCKS TECHNOLOGY CO., LTD**  
**ZIP 231, 12F, NO.190, CHUNG-HSIN RD., SEC.2, HSIN-TIEN CITY, TAIPEI**  
**COUNTRY, TAIWAN, R.O.C.**  
**TEL: 886-2-2911-3080 FAX: 886-2-2914-1712**

It is because the surface of the device does not enough to indicate the FCC statement. For this reason, I-ROCKS TECHNOLOGY CO., LTD proposes those statements is showing on the user manual and the device is carrying the FCC ID number only. The figure2 is showing the FCC ID location.




figure 2

Sincerely,

I-ROCKS TECHNOLOGY CO., LTD

*Brain Wu*

Brain Wu  
Technical Support Manager

**I-ROCKS TECHNOLOGY CO., LTD.**

