Photo No. 37: bottom view



Photo No. 38: side view left



Photo No. 39: side view right



2.7 Variant ID #54

2.7.1 Radiated EUT, serial number 65702

Photo No. 40: rear view



Photo No. 41: front view



Photo No. 42: top view

Photo No. 43: bottom view

Photo No. 44: side view left



Photo No. 45: side view right



2.8 Variant ID #56

2.8.1 Radiated EUT, serial number 65602

Photo No. 46: rear view



Photo No. 47: front view

Photo No. 48: top view



Photo No. 49: bottom view



Photo No. 50: side view left



Photo No. 51: side view right



2.8.2 Radiated EUT, serial number 65604

Photo No. 52: rear view



2.9 Variant ID #57

2.9.1 Radiated EUT, serial number 65903

Photo No. 53: rear view



Photo No. 54: front view

Photo No. 55: top view



Photo No. 56: bottom view



Photo No. 57: side view left



Photo No. 58: side view right



2.10 Variant ID #62

2.10.1 Radiated EUT, serial number 66305

Photo No. 59: rear view



Photo No. 60: front view

Photo No. 61: top view



Photo No. 62: bottom view



Photo No. 63: side view left



Photo No. 64: side view right



2.10.2 Radiated EUT, serial number 66304

Photo No. 65: rear view



3 Revision History
-0 Initial Version
-1 Revision: administrative modification/correction
Change of HVIN
This test report 21086128-23003-1 **replaces the previous test report 21086128-23003-0**

End of Annex