

Annex I. Analysis of Simultaneous Transmission SAR.

There is no simultaneous transmission configuration in this device .