



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 27, 2006

RE: Inventec Appliances (Jiangning) Corporation

FCC ID: UPMCA11001

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) Please supply a parts list for this device.
- 2.) Please supply a tune up procedure for this device.
- 3.) Please supply a corrected Form 731 with an email address for the technical contact.
- 4.) Please supply both frequency tolerance and emission designator on Form 731.
- 5.) The Manual contains none of the compliance information required for Licensed cellphones. Please review and provide.
- 6.) Please provide a more complete and detailed block diagram. Please pay particular attention to providing details for the "CDMA Module".
- 7.) FYI: SAR reports should always go inside the "RF Exposure" folder, and not under "Test Reports".
- 8.) Traditionally, IS-95/98 CDMA with 1.25MHz bandwidth will use a RBW of 30KHz when making occupied bandwidth measurements. The plots you provided in 4.5 use a RBW of 300KHz. Kindly revise this measurement while keeping the span at 5MHz.
- 9.) Please provide the voltage and current through the final RF amplification device as specified in Part 2 of the Rules.
- 10.) Please provide a justification for any emission designator requested on Form 731 in the Test Report.
- 11.) The SAR reports have Z-axis plots which do not follow the classical fit curve. Usually this indicates that some problem may have occurred in the Test Setup with reflections inside the phantom, or from the surface of the fluid. Please review your data and comment. In addition, a Z-axis plot should be presented for both highest body and highest head SAR values.
- 12.) The SAR report gives no indication of separation distance in the body-worn photographs.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.