

Area is applied by final assembly line

Area is applied after mode typification



2:1

Production Code (ZAYWW Dhhmm):

	Meaning	Example
Z	Final Assembly Line Identification	A = EM D20 B = EM D40 C = EM D20-2
A	Initial Version of D501/D601	
Y	Year (last digit)	6 = 2016
WW	Calendar week	
D	Day of week	1 = Monday, 7 = Sunday
hh	Hours	24h mode
mm	Minutes	

Mode Indication:

X	Meaning
1	clean
2	clean, soft
3	clean, soft, polish
4	clean, soft, polish, massage
5	clean, pro clean, soft, polish, massage



RESTRICTED	Project: D601			No: 90968274			Sheet: 1 of 1
	Article: D601 Type Plate MN/NA						Scale: 1 : 1
							Tolerance: ± 0,3
							Risk Classification: n/a
	Process: Housing: Mold Marking						BRAUN
	Process: Bottom: Laser Marking						
	Drawn	01.11.2016	Gasseling	00	HZ	01.11.2016	Gasseling
	Released			Index	Remarks	Date	Name