

Appendix F. SAR Test Setup Photos

Extremity Exposure Condition



Front Face at 0 mm



Front Face with Lightbar at 0 mm



Front Face with Scanner at 0 mm

Extremity Exposure Condition_For NFC



Front Face at 0 mm



Front Face with Lightbar at 0 mm



Front Face with Scanner at 0 mm

PD Exposure Condition



Front Face at 2 mm



Front Face with Lightbar at 2 mm



Front Face with Scanner at 2 mm