

Appendix F. SAR Test Setup Photos

Extremity Exposure Condition



Front Face at 0mm




Front Face with Lightbar at 0mm




Front Face with Scanner at 0mm


PD Exposure Condition



Front Face at 2mm



Front Face with Lightbar at 2mm



Front Face with Scanner at 2mm