

Appendix F. SAR Test Setup Photos

Hotspot Exposure Condition



Front at 10 mm



Top Side at 10 mm



Left Side at 10 mm



Right Side at 10 mm

Body-worn Exposure Condition



Front with Holster at 0 mm



Left Side at 0 mm



Right Side at 0 mm



Left Side with Holster at 0 mm



Right Side with Holster at 0 mm



Left Side with Holster with Headset at 0 mm



Right Side with Holster with Headset at 0 mm

Product Specific Exposure Condition



Back at 0 mm

PD Test Setup Photo



Front with holster at 2 mm



Back at 2 mm



Left Side with holster at 2 mm



Right Side with holster at 2 mm

Supplemental SAR Setup Photo



Front at 25 mm



Left Side at 25 mm



Right Side at 25 mm