Appendix D. SAR Test Setup Photos

Head Exposure Condition

Right Cheek at 0mm

Right Tilted at 0mm

Left Cheek at 0mm



Left Tilted at 0mm

Hotspot Exposure Condition

Front at 10 mm

Back at 10 mm



Right Side at 10 mm



Left Side at 10 mm

Top Side at 10 mm

Bottom Side at 10 mm

Body-worn Exposure Condition

Front at 15 mm

Back at 15 mm



Back with Holster at 0 mm

Product Specific Condition

Back at 0 mm

Left Side at 0 mm



Right Side at 0 mm

Front at 0 mm

Top Side at 0 mm

Bottom at 0 mm

PD Condition

Front at 2 mm

Back at 2 mm



Right Side at 2 mm



Left Side at 2 mm



Top Side at 2 mm

.