

Appendix G. SAR Test Setup Photos

<without bumper>

Head Exposure Condition



Right Cheek at 0mm



Right Tilted at 0mm



Left Cheek at 0mm



Left Tilted at 0mm

Hotspot Exposure Condition



Front at 10 mm



Back at 10 mm



Left Side at 10 mm



Right Side at 10 mm



Top Side at 10 mm



Back at 25 mm

Body-worn Exposure Condition



Front+ Holster at 0 mm



Back + Holster at 0 mm



Front at 25mm

Body-worn Exposure Condition



Wrist at 0 mm



Wrsit+Headset 1 at 0 mm



Wrsit+Headset 2 at 0 mm



Wrsit+Headset 3 at 0 mm

Product Specific Exposure Condition



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm

<with bumper>

Head Exposure Condition



Right Cheek at 0mm



Right Tilted at 0mm



Left Cheek at 0mm



Left Tilted at 0mm

Hotspot Exposure Condition



Front at 10 mm



Back at 10 mm



Left Side at 10 mm



Right Side at 10 mm



Top Side at 10 mm



Back at 25 mm

Body-worn Exposure Condition



Front+ Holster at 0 mm



Back + Holster at 0 mm



Front at 25mm

Product Specific Exposure Condition



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm

PD Exposure Condition



Front at 2 mm



Back at 2 mm



Back at 25mm