





EUT Mode

802.11ax HE20 106RU53


Plot on 5955 MHz




Plot on 6195 MHz



Plot on 6535 MHz



Plot on 6695 MHz






EUT Mode


802.11ax HE20 106RU54

Plot on 6415 MHz



02:11:55 PM 06/11/2025

Plot on 6855 MHz



04:20:11 PM 06/11/2025




MIMO <Ant. 1+2(2)>


EUT Mode

802.11ax HE20 FullIRU


Plot on 5955 MHz




Plot on 6195 MHz



Plot on 6415 MHz




Plot on 6535 MHz






Plot on 6695 MHz



Plot on 6855 MHz






EUT Mode


802.11ax HE20 26RU0

Plot on 5955 MHz



09:45:46 AM 06/11/2025

Plot on 6535 MHz




02:26:57 PM 06/11/2025



EUT Mode


802.11ax HE20 26RU4

Plot on 6195 MHz



11:22:55 AM 06/11/2025

Plot on 6695 MHz




03:05:33 PM 06/11/2025



EUT Mode


802.11ax HE20 26RU8

Plot on 6415 MHz



12:02:21 PM 06/11/2025

Plot on 6855 MHz




03:58:16 PM 06/11/2025



EUT Mode


802.11ax HE20 52RU37

Plot on 5955 MHz



10:25:43 AM 06/11/2025

Plot on 6535 MHz




02:33:14 PM 06/11/2025



EUT Mode


802.11ax HE20 52RU38

Plot on 6195 MHz



11:35:29 AM 06/11/2025

Plot on 6695 MHz




03:20:03 PM 06/11/2025



EUT Mode


802.11ax HE20 52RU40

Plot on 6415 MHz



12:33:32 PM 06/11/2025

Plot on 6855 MHz




04:12:58 PM 06/11/2025



EUT Mode


802.11ax HE20 106RU53

Plot on 5955 MHz




10:50:53 AM 06/11/2025

Plot on 6195 MHz




11:47:08 AM 06/11/2025

Plot on 6535 MHz



02:41:36 PM 06/11/2025

Plot on 6695 MHz




03:26:54 PM 06/11/2025



EUT Mode


802.11ax HE20 106RU54

Plot on 6415 MHz



02:14:46 PM 06/11/2025

Plot on 6855 MHz



04:23:32 PM 06/11/2025




MIMO <Ant. 1+2(1)>


EUT Mode

802.11ax HE40 FullIRU


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6405 MHz




Plot on 6565 MHz






Plot on 6685 MHz



Plot on 6845 MHz







EUT Mode

802.11ax HE40 242RU61


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6565 MHz



Plot on 6685 MHz






EUT Mode


802.11ax HE40 242RU62

Plot on 6405 MHz



10:14:33 AM 06/12/2025

Plot on 6845 MHz



11:18:08 AM 06/12/2025




MIMO <Ant. 1+2(2)>


EUT Mode

802.11ax HE40 FullIRU


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6405 MHz




Plot on 6565 MHz






Plot on 6685 MHz



Plot on 6845 MHz






EUT Mode


802.11ax HE40 242RU61

Plot on 5965 MHz




05:13:36 PM 06/11/2025

Plot on 6205 MHz




05:48:32 PM 06/11/2025

Plot on 6565 MHz



10:37:16 AM 06/12/2025

Plot on 6685 MHz




10:52:08 AM 06/12/2025



EUT Mode


802.11ax HE40 242RU62

Plot on 6405 MHz



10:17:08 AM 06/12/2025

Plot on 6845 MHz



11:20:01 AM 06/12/2025




MIMO <Ant. 1+2(1)>

EUT Mode


802.11ax HE80 FullRU

Plot on 5985 MHz




12:14:11 PM 04/04/2025

Plot on 6225 MHz




12:24:29 PM 06/06/2025

Plot on 6385 MHz



05:29:40 PM 04/09/2025

Plot on 6625 MHz



05:56:12 PM 06/09/2025